RISO, INC. **PARTS CHANGE INFORMATION**

PART: SET PLATES / JOB SEPERATOR BRACKETS **ISSUE #: 020**

JAPAN: TI-050

NEW PART NUMBER: See Part Numbers Below NEW DESCRIPTION: SET PLATES / JOB SEPERATOR BRACKETS OLD PART NUMBER: OLD DESCRIPTION:	[X] New [ ] Modified [ ] Obsolete [ ] Other
Compatible: [X] Not Compatible: [ ] Old/Obsolete: [N]	

CHANGE REASON	MANUFACTURING CUT-IN	MODEL(S):
[ ] Cost Effective [ ] Eliminate Claims [X] Easier Operation [ ] Other	SERIAL #: RC4000 - 94411028 RC4500 - 91515624 RC5600 - 91421021 RC5800 - 92451421	RC SERIES (Excluding 6300)

The Set Plates and Job Seperator Brackets have been changed to allow a 45 degree tilt to the Receiving Tray. The new parts improve paper stacking in the Receiving Tray.



011-13144 Set Plate F; P-Rcv-T
011-13146 Set Plate R; P-Rcv-T



011-13915 Bracket II; Job Seperator
011-13916 Boss; Job Seperator